



VEHICLE FACTORS ATTACHMENT

End-Dump Semitrailer Maintenance Log

Rushville, IL

HWY24MH005

(3 pages)

1201

- 6-1-19 replaced right ~~side~~ mud flap
- 6-10-19 New complete Brake chamber on Left
Front axle, 4 New virgin tires on rear axle
- 7-2-19 1 2 recap tires on right front of trailer,
New brake on right front, New wheel seal
on right front, rewired whole trailer, New
wires up left side of trailer, New pigtailed
on rear of trailer
- 10-31-19 New Brake on Left front ~~axle~~ axle,
New wheel seal on Left front axle
- 3-4-20 New brakes rear axle, New slack adj. rear axle,
2 New tires right rear axle, used tire
Left rear inside
- 8-17-20 2 New slack adjusters - Right front, Right rear
New complete Brake chamber right front
Service call to good hope - 2 New tires
on left front
- 8-25-21 New tarp, used pipe Left one
- 7-14-22 NEW BRAKES, CAMS, BUSHINGS, SWINGARM
BUSHINGS, SHOCKS ON REAR AXLE, 1
SHOCK ON LT FRONT AXLE, BRAKE CHAMBER
R.H REAR
- 7-18-23 Right Front AXLE wheel seal New Brakes New
SCAM Bushing Repaired SLACK ADJUSTER
- 7-7-23 1 New mud Flap Right side
- 7-22-23 Two used Tires Right side Rear Axle

#201

- 11-22-23 Two new Tires R. Front AXLE
- 11-27-23 New Slack ADJUSTER R. Front AXLE New VALVE
Back of AIR TANK (110700 Spring Brake)
- 12-21-23 New LR Brakes + Drum 1 used tire Rear AXLE
- 12-21-23 REPAIRED TARP 2ND GREASE
- 1-15-24 New Brakes Front AXLE 1 new Drum R side
- 1-15-23 Installed new electric TAPPS
- 3-4-24 Repaired Bent ARM BU TARP AT Rear of
TRAILOR Lengthened TARP Pipe
- ~~3-8-24~~
- 3-8-24 greased trailer, checked Lights, checked hub oils