



**Photo 1 – Initial Impact Crater (NTSB Photo)**





**Photo 2 – Main Wreckage (NTSB Photo)**






**Photo 3 - Main Wreckage (NTSB Photo)**





**Photo 4 - Main Wreckage (NTSB Photo)**





**Photo 5 – Impact Damage to Trees (NTSB Photo)**





**Photo 6 – Engine and Propeller (NTSB Photo)**





**Photo 7 – Propeller Blade (NTSB Photo)**





**Photo 8 – Engine-driven Vacuum Pump (NTSB Photo)**





**Photo 9 – Vacuum Pump Rotor and Vanes (NTSB Photo)**






Photo 10 – 1200.aero Display of Accident Flight (NTSB Photo)