




**Photo 1 – Left Side of Fuselage Wreckage.**



**Photo 2 – Recovery of Empennage**





**Photo 3 – Unloading Wreckage in Juneau, Alaska**



**Photo 4 – NTSB IIC Brice Banning with Recovered CVR Onboard Recovery Vessel**