



Photo 1 – N72536 Cessna 120 wreckage at the accident site. (Photograph compliments of owner.)



Photo 2 - Right wing and fuselage damage. (Photograph compliments of owner.)