

ANC24LA026

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Accident Aircraft (Courtesy of FAA)



Photograph 2 - Back Right View of Aircraft (Courtesy of FAA)



Photograph 3 - View of damage to fuselage (Courtesy of Owner)