



Photo 1 – View of damaged tailcone (courtesy of the FAA)



Photo 2 – View of damaged left wing (courtesy of the FAA)