



**Photo 1 – View of N12171 balloon on its side after impacting terrain (courtesy of local law enforcement officer)**