



**Photo 1 – View of damage to left wing (photo courtesy of the pilot)**



**Photo 2 – View of damage to left elevator (photo courtesy of the pilot)**