



**Photo 1– View of airplane with damaged left wing (photo courtesy of local law enforcement)**



**Photo 2 – View of secured gas cap with AVGAS ONLY sticker (courtesy of local law enforcement)**