



Photo 1 – View of nosed over airplane with a damaged left-wing lift strut (courtesy of the pilot)



Photo 2 – View of nosed over airplane with damaged tailcone (courtesy of the pilot)