



Photo 1 – Aerial view of the community center and accident site (courtesy of Touchstone District Services, in partnership with Harris County Emergency Services District #48).



Photo 2 – Aerial view of the accident site (courtesy of Touchstone District Services, in partnership with Harris County Emergency Services District #48).



Photo 3 – Security camera footage of the airplane impacting the parking lot (courtesy of the Mason Creek Community Center).



Photo 4 – Security camera footage of the airplane impacting the building (courtesy of the Mason Creek Community Center).




Photo 5 – Accident site diagram (courtesy of Textron Aviation).



Photo 6 – View of the building.



Photo 7 – View of the parking lot and the building.



Photo 8 – View of the pool deck and the pool.



Photo 9 – View of the pool deck and the pool.



Photo 10 – View of the wreckage layout (courtesy of Textron Aviation).




Photo 11 – View of the wreckage layout (courtesy of Textron Aviation).



Photo 12 – Front view of the engine (courtesy of Lycoming Engines).



Photo 13 – Left side view of the engine (courtesy of Lycoming Engines).



Photo 14 – View of the propeller.



Photo 15 – View of the propeller.