



Photo 1 – Main wreckage at accident site



Photo 2 – View of cabin and main wreckage at accident site



Photo 3 – Enlarged photograph of accident airplane avionics



Photo 4 – Image of avionics during flight on December 22, 2019 (Courtesy of Passenger from Prior Flight in Accident Airplane)



Photo 5 – Image of avionics during flight on December 22, 2019 (Courtesy of Passenger from Prior Flight in Accident Airplane)