



**Photo 1 – Main Wreckage**





**Photo 2 – Quartering View of Main Wreckage**





**Photo 3 – View of Accident Site from Tail**






**Photo 4 – Engine at Examination Facility**






**Photo 5 – Engine and Accessory Case**





**Photo 6 – Wreckage Path Diagram (Figure 1 in Factual Report)**





**Photo 7 – Terrain Elevations Along Flight Path (Figure 2 in Factual Report)**