



**Photo 1 – Front view of the airplane (courtesy of the Federal Aviation Administration).**



**Photo 2 – Left side view of the underside of the fuselage (courtesy of the Federal Aviation Administration).**



**Photo 3 – Right side view of the underside of the fuselage (courtesy of the Federal Aviation Administration).**



**Photo 4 – Close up view of the substantial damage sustained to the bottom of the fuselage (courtesy of the Federal Aviation Administration).**



**Photo 5 – Close up view of the cockpit-based main landing gear lever and status indicator lights (courtesy of the Federal Aviation Administration).**