



**Photo 1 – Right side view of the airplane in the field (courtesy of the Federal Aviation Administration).**





**Photo 2 – Rear view of the airplane in the field (courtesy of the Federal Aviation Administration).**





**Photo 3 – Front view of the airplane after it was recovered from the field to a hangar (courtesy of the Federal Aviation Administration).**





**Photo 4 – Close up view of the substantial damage sustained to the left wing (courtesy of the Federal Aviation Administration).**





**Photo 5 – Close up view of the substantial damage sustained to the engine mount (courtesy of the Federal Aviation Administration).**