



**Photo 1 – Right side view of the airplane (courtesy of the Federal Aviation Administration).**



**Photo 2 – Rear view of the substantial damage sustained to the right wing (courtesy of the Federal Aviation Administration).**



**Photo 3 – Rear view of the substantial damage sustained to the right horizontal stabilizer (courtesy of the Federal Aviation Administration).**