



**Photo 1 – View of the runway with the airplane resting in the trees to the left of the runway (courtesy of the Federal Aviation Administration).**



**Photo 2 – View of the rear of the airplane after it came to rest (courtesy of the Federal Aviation Administration).**



**Photo 3 – Close up view of the right wing (courtesy of the Federal Aviation Administration).**