



Photo 1 – Accident site (Courtesy of Farmington airport operations)



Photo 2 – Aircraft from behind right wing (Courtesy of Farmington airport operations)



Photo 3 – Midspan right wing from behind (Courtesy of Farmington airport operations)