



Photo 1 – Left side view of the airplane after it was recovered (courtesy of the Federal Aviation Administration).



Photo 2 – Close-up view of the separated nose wheel assembly (courtesy of the Federal Aviation Administration).



Photo 3 – Close-up frontal view of the underside of the fuselage (courtesy of the Federal Aviation Administration).



Photo 4 – Close-up left side view of the underside of the fuselage (courtesy of the Federal Aviation Administration).