



**Photo 1 – View of the substantial damage sustained to the underside of the fuselage (courtesy of the Federal Aviation Administration).**



**Photo 2 – Closeup view of the substantial damage sustained to the underside of the fuselage (courtesy of the Federal Aviation Administration).**



**Photo 3 – View of the substantial damage sustained to the underside of the fuselage (courtesy of the Federal Aviation Administration).**



**Photo 4 – Closeup view of the substantial damage sustained to the underside of the fuselage (courtesy of the Federal Aviation Administration).**