



Photo 1 – View of the runway prior to where the airplane came to rest inverted (courtesy of the Federal Aviation Administration).



Photo 2 – Front view of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 3 – Front view of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 4 – Rear view of the inverted airplane (courtesy of the Federal Aviation Administration).