

CEN23FA125

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall front view of the helicopter.



Photograph 2 - Overall side view of the helicopter.



Photograph 3 - Overall rear view of the helicopter.



Photograph 4 - Overall side view of the helicopter.




Photograph 5 - View of the cockpit and cabin areas.



Photograph 6 - View of the cockpit and cabin areas.



Photograph 7 - View of the tail rotor system.



Photograph 8 - View of the instrument panel.



Photograph 9 - View of the navigation lights and anti-collision (strobe) light switches.



Photograph 10 - View of the anti-collision (strobe) light.



Photograph 11 - View of the anti-collision (strobe) light.



Photograph 12 - View of the bottom of the engine.



Photograph 13 - View of the top of the engine.



Photograph 14 - View of the pinata found at the accident site.



Photograph 15 - View of the helicopter after it was recovered from the accident site.