

CEN25LA092

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the left side of the inverted airplane at the accident site (courtesy of the flight instructor)



Photograph 2 - View of the front of the inverted airplane at the accident site (courtesy of the flight instructor)



Photograph 3 - View of the right side of the inverted airplane at the accident site (courtesy of the flight instructor)