



Photo 1 – Forward View of Accident Airplane (Courtesy of Federal Aviation Administration)



Photo 2 – View of Top of Instrument Panel and Engine Cowl (Courtesy of Federal Aviation Administration)



Photo 3 – Accident Airplane Prior to Examination



Photo 4 – Forward View of Windshield Before Examination



Photo 5 – Side View of Windshield Remnants