



**Photo 1 – View of the airplane looking to the south. The student pilot’s private airstrip is located in the upper right corner of the photograph near the trees.**



**Photo 2 – View of the front of the airplane.**



**Photo 3 – View of the left side of the airplane.**



**Photo 4 – View of the right side of the airplane.**




**Photo 5 – View of the left side of the engine.**



**Photo 6 – View of the right side of the engine.**



**Photo 7 – View of the propeller.**



**Photo 8 – View of the carburetor heat control in the cockpit.**





**Photo 9 – View of the carburetor intact (courtesy of Textron Aviation).**



**Photo 10 – View of the carburetor disassembled (courtesy of Textron Aviation).**



**Photo 11 – View of the fuel placard (courtesy of Textron Aviation).**



**Photo 12 – View of a fuel sample from the left fuel tank (courtesy of Textron Aviation).**



**Photo 13 – View of the propeller removed from the engine (courtesy of Textron Aviation).**