



**Photo 1 – View of nosed over airplane with damaged right wing lift strut (courtesy of the FAA)**



**Photo 2 – View of nosed over airplane with damaged rudder (courtesy of the FAA)**