



Photo 1 – View of the gray metal fence that was impacted by the airplane, while on the final approach to runway 14 (courtesy of the Federal Aviation Administration).



Photo 2 – Right side view of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 3 – Left side view of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 4 – Rear view of the inverted airplane (courtesy of the Federal Aviation Administration).