



Photo 4 – View of accident airplane fuselage damage (photo courtesy of Air Tractor).



Photo 1 – View of accident airplane on left side (photo courtesy of Air Tractor).



Photo 3 - View of undercarriage of accident airplane (photo courtesy of Air Tractor).



Photo 2 – View of Trotter Controls Gen III Firegate in the off position (photo courtesy of Air Tractor).