



Photo 1 – View of accident airplane (photo courtesy of local law enforcement).



Photo 2 - View of left and right wing damage (photo courtesy of local law enforcement).