



Photo 1 – Historical photo of the accident airplane (courtesy of Kathryn’s Report).



Photo 2 – Overview of the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the front of the airplane (courtesy of the Federal Aviation Administration).



Photo 4 – View of the left side of the airplane (courtesy of the Federal Aviation Administration).



Photo 5 – View of the rear of the airplane (courtesy of the Federal Aviation Administration).



Photo 6 – View of the right side of the airplane (courtesy of the Federal Aviation Administration).



Photo 7 – View of the propeller, the engine, and the cockpit (courtesy of the Federal Aviation Administration).



Photo 8 – View of the engine (courtesy of the Federal Aviation Administration).