

CEN23FA084

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of the accident site.



Photograph 2 - View of the front of the airplane at the accident site.



Photograph 3 - View of the left side of the airplane at the accident site.



Photograph 4 - View of the rear of the airplane at the accident site.



Photograph 5 - View of the right side of the airplane at the accident site.



Photograph 6 - View of the propeller and the engine at the accident site.



Photograph 7 - View of the airplane being recovered at the accident site.



Photograph 8 - View of the airframe during layout.



Photograph 9 - View of the propeller and the engine during the layout.



Photograph 10 - View of the wings during the layout.



Photograph 11 - View of part of the empennage during the layout.



Photograph 12 - View of the propeller blades during the layout.