



Photo 1 – View of damaged blade (Photo courtesy of the operator)



Photo 2 – Additional picture of damaged blade (Photo courtesy of the operator)