

Photo 1 – Exemplar picture of the accident helicopter (Photo courtesy of USCG)



Photo 2 – Pop-out float found on beach (Photo courtesy of Deckload Aviation)




Photo 3 – Additional view of pop-out float (Photo courtesy of Deckload Aviation)



Photo 4 – Float serial no. (Photo courtesy of Deckload Aviation)