



Photo 1 – Damage to right wing of N9201A



Photo 2 – Rudder damage to N197CV



Photo 3 – Airplanes in flight (Provided by pilot of N9201A)