



**Photo 1 – Debris in Tree (Provided by Sioux Fall Police Department)**



**Photo 2 – Impact Marks on Building (Provided by Sioux Fall Police Department)**



**Photo 3 – Airplane Wreckage in Tree (Provided by Sioux Fall Police Department)**



**Photo 4 – Debris Field (Provided by Sioux Fall Police Department)**



**Photo 5 – Debris Field (Provided by Sioux Fall Police Department)**



**Photo 6 – Engine and Propeller Assembly (Provided by Sioux Fall Police Department)**



**Photo 7 – Engine and Propeller Assembly (Provided by Sioux Fall Police Department)**



**Photo 8 – Debris Field (Provided by Sioux Fall Police Department)**





**Photo 9 – Main Wreckage (Provided by Sioux Fall Police Department)**