



Photo 1 – Main wreckage in river (provided by Carlton County Sheriff)



Photo 2 – Snow on empennage of airplane in river (provided by Carlton County Sheriff)



Photo 3 – Fuselage of airplane in river (provided by Carlton County Sheriff)



Photo 4 – Forward fuselage of airplane



Photo 5 – Engine and propeller (Provided by FAA)



Photo 6 – Right Wing



Photo 7 – Right Wing



Photo 8 – Left Wing



Photo 9 - Altimeter