

CEN23LA323

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on the runway (Courtesy of Whittman Regional Airport)



Photograph 2 - Airplane on the runway (Courtesy of Whittman Regional Airport)



Photograph 3 - Left Main Landing Gear and Fuselage