



**Photo 1 – Automobile Video of Airplane Immediately Before Impact. (Courtesy of Ocala Police)**



**Photo 2 – Imprint of Airplane on Highway. Note Left and Right Propeller Marks in Asphalt. (Courtesy of Ocala Police)**



**Photo 3 – Imprint of Airplane on Highway. Final Wreckage Location in Background (Courtesy of Ocala Police)**



**Photo 4 – Airplane Wreckage at Final resting Site; View Looking from Nose to Tail.**



**Photo 5 – View of Airplane Wreckage Looking Down Left Wing to the Fuselage.**



**Photo 6 – View of Left Engine, Wing and Propeller Damage.**



**Photo 7 – Right Front Quartering View Looking at Entire Wreckage.**



**Photo 8 – View of Right Engine and Propeller Damage; Note the Engine is Detached and Upside Down.**





**Photo 9 – View of Damaged Instrument Panel and Throttle/Control Levers.**



**Photo 10 – View of Left Engine in Hoist Prior to Examination.**



**Photo 11 – View of Right Engine in Hoist Prior to Examination.**