



Photo 1 – Aft view of airplane looking forward. (Courtesy of FAA)



Photo 2 – Right profile view of airplane in the grass off the runway. (Courtesy of FAA)



Photo 3 – View of collapsed landing gear and propeller damage. (Courtesy of FAA)