



Photo 1 – Closeup view left side of cockpit showing fuselage and engine compartment damage. (Courtesy of FAA)



Photo 2 – Right side profile view of airplane damage. Note crumpled fuselage. (Courtesy of FAA)



Photo 3 – Closeup photo of right wing bend upwards. (Courtesy of FAA)