



**Photo 1 – View of helicopter as it rests on its right side. Note damage to rotor blades, mast, and cockpit. (Courtesy of FAA)**



**Photo 2 – View of helicopter from topside. Note damage to fuselage and rotor blades. (Courtesy of FAA)**



**Photo 3 – View of cockpit damage after the helicopter was moved into the hanger. (Courtesy of FAA)**