



Photo 1 – View of right side of airplane resting on service road. (Courtesy of FAA)



Photo 2 – Head on view of airplane showing collapsed nose gear and damage to left wing. (Courtesy of FAA)