



Photo 1 – Overall view of airplane damage. (Courtesy of FAA)



Photo 2 – Closeup of engine compartment and airframe damage. (Courtesy of FAA)



Photo 3 – View of propeller strike marks in the ground. (Courtesy of FAA)



Photo 4 – Aft view of airplane and ground scars after it skidded to a stop. (Courtesy of FAA)