



**Photo 1 – View of left front quarter of the airplane as it rests on the runway. Note damaged engine compartment.
(Courtesy of the FAA)**



Photo 2 – View of front of the airplane as it rests on the runway. Note damaged engine compartment. (Courtesy of the FAA)



Photo 3 – View of right side of the airplane as it rests on the runway. Note damaged engine compartment. (Courtesy of the FAA)