



**Photo 1 – View of left side of inverted airplane about forty feet off runway. (Courtesy of FAA)**



**Photo 2 – Closeup view of left side of inverted airplane. Note left wing damage. (Courtesy of FAA)**



**Photo 3 – View of right side of inverted airplane located about forty feet from runway. (Courtesy of FAA)**