



Photo 1 – Overhead view of left wing looking southwest towards main wreckage in background.



Photo 2 – Overhead view of main wreckage.



Photo 3 – Ground level view of main wreckage looking north.



Photo 4 – View of final resting spot of left wing as it was discovered. Wing is upside down with the landing gear extended. Note the fractured wing spar.



Photo 5 – View of left wing upright showing top of wing and control cable tears and skin buckling.



Photo 6 – Close up view of left-wing lower spar cap fracture.



Photo 7 – Close up view of left fuselage wing spar and fracture surface.