



Photo 1 – View of left side of airplane damage at the accident site.



Photo 2 – View of underside of wreckage at the accident site showing the cockpit, fuselage, engine and wings.



Photo 3 – Close up view of rudder and elevator. Note the bent rudder trim tab.



Photo 4 – Close up of propeller.