



Photo 1 – View of airplane and damage as it sits on the runway. Note the fuselage wrinkles and the left landing gear bent under the fuselage. (Courtesy of CJR Airport)