



**Photo 1 – Overall view of airplane damage as it rests in the corn field (Courtesy of FAA)**



**Photo 2 – View of empennage damage to elevator and rudder. (Courtesy of FAA)**



**Photo 3 – Right side view of fuselage damage. (Courtesy of FAA)**



**Photo 4 – Cockpit controls and instrument panel view. (Courtesy of FAA)**



**Photo 5 – Closeup view of fuel selector lever. Note the up position for the right tank. (Courtesy of FAA)**