



ATTACHMENT 2

AIRWORTHINESS GROUP FACTUAL REPORT

NTSB No. WPR18MA087

**Accident Site Laser Scan Image Comparisons
(5 Pages)**



Figure 1. Accident site





Figure 2. Accident site after wreckage removal






Figure 4. Laser scan comparison




Figure 5. Laser scan comparison (birds-eye view)